Equipment : RWC2100F Analog Radio Tester

Version	Date	Description
V1.076	23/OCT/2026	[Bug fixed] 1. Fixed an issue with file deletion. [Functions] 1. Removed the SNR measured value. 2. Added a delta checkbox to the Audio dBu Level section to enable SNR measurement.
V1.075	12/AUG/2026	[Bug fixed] 1. Correction of Remote Command Errors CONF:FM_TX:EON_PTYPE → CONF:FM_TX:EON_PTY READ:FM_TX:EON_PTYPE → READ:FM_TX:EON_PTY [Functions] 1. Change to FM Frequency Adjustment Step 100 kHz → 10 kHz
V1.074	19/JUN/2026	[Bug fixed] 1. Fixed a file manager operation error that occurred when selecting the last item in the file list. [Functions]
V1.073	03/JUN/2026	[Bug fixed] 1. EON-Related Function Updates a. Removed the DEFAULT setting for EON PTYPE. b. When EON SWITCH is turned ON, the Program Type (PTY) of the target channel corresponding to the selected EON PTYPE is automatically configured and sends the EON_PTYPE Command. [Functions]
V1.072	01/JUN/2026	[Bug fixed] [Functions] 1. Removed EON Tab in FM channel 2, and channel 3
V1.071	11/MAY/2026	[Bug fixed] [Functions] 1. Added EON_PTYPE value configuration in RDS
V1.070	15/APR/2026	[Bug fixed] [Functions] 1. Prevented multiple instances of the RWC2100F application from running simultaneously.
V1.063	15/MAR/2026	[Bug fixed] 1. Fixed freezing issue while loading a workspace file 1. Added missing remote commands in the script function [Functions] 1. Added a feature to force a connection to the RWC2100F even if it is already occupied by another user.
V1.062	15/DEC/2023	[Bug fixed] 1. Fixed an intermittent application disappearance issue. 2. Fixed an issue where the Audio Analyzer measurement values

		were not updated after reconnecting the RWC2100F. [Functions]
V1.0611	29/OCT/2023	[Bug fixed] 1. Fixed issue with setting the last frequency in the AF list. 2. Fixed synchronization error between App and Equipment after changing the AF frequency. [Functions]
V1.061	23/OCT/2023	[Bug fixed] 1. Fixed level scaling function in the Audio Analyzer [Functions] 1. Added DI (Decoder Identification) variable to FM RDS mode. It indicates different operating modes to switch individual decoders on or off and to indicate if PTY codes in the transmission are dynamically switched. 2. Added Tag information up to four entries, an increase from the previous limit of two. 3. Added variables that allow the user to set the item toggle bit and item running bit when transmitting RDS Tag information.. 4. Increase AF frequencies up to 24 for A mode, 12 for B mode. 5. Added a capturing graph function in the Audio Analyzer. 6. Added a low-pass filter function(Off, 1kHz-20kHz) 7. Added more measured audio values such as Vrms, Vpp, dBu, Separation.
V1.054	07/JUL/2023	[Bug fixed] 1. [Functions] 1. UdpClient port number is changed 50000 →21000 2. modified Audio Analyzer Spectrum functions a. LOG scale view option b. Left/Right split option
V1.052	20/MAR/2023	[Bug fixed] 1. The position of the 'TIME' button of RDS is aligned. [Functions] 1. FW V1.052 Compatible
V1.050	12/JAN/2023	[Bug fixed] 1. Fixed application crash problem while saving RDS data. [Functions] 1. Added a cursor function in waveform and spectrum display 2. Added Vrms and Vpp measurements to Audio Analyzer. 3. Added weighted filters (OFF, A_WEIGHT, C_WEIGHT, CCIR) to Audio Analyzer.
V1.041	12/DEC/2022	[Functions] 1. Added External Audio input gain parameter.
V1.040	02/DEC/2022	[Bug fixed] 1. Fixed a disappearing problem with the download information window while downloading multiple content files. 2. Not allow to download content files that contain non-english characters [Functions] 1. Added the EXT_AUDIO_IN option in the AUDIO SOURCE parameter in the FM/AM transmitter
V1.032	30/NOV/2022	[Bug fixed] [Functions]

		1. PLAY ALL FILES option added in the FILE MODE of the AUDIO SOURCE for all FM/AM channels
V1.031	07/JUN/2022	[Bug fixed] 1. Fixed the problem that TMC message is not sent intermittently [Functions] 1. Made it possible to edit AF, TMC, and EON without connection the RWC2100F 2. Made it possible to open a workspace without connection the RWC2100F
V1.030	18/MAY/2022	[Bug fixed] [Functions] 1. Improved the TMC function. - limited 5 TMC messages to unlimited numbers of it - Added editable TMC messages tables for all 3 RDS channels - send or skip option for each TMC message
V 1.024	30/MAR/2022	[Bug fixed] 1. fixed the problem of “READ:FM_TX:EON_PS_NAME?” remote command. [Functions]
V 1.023	15/NOV/2021	[Bug fixed] 1. fixed the incorrect loading parameters of the “Stand alone/read from RWC2100F” such as CH1/2 FM/AM TX selection, wave contents file name. [Functions] 1. removed the list of the “Stand Alone” function
V 1.022	30/JUN/2021	[Bug fixed] 1. improve File download stability, and retransmission.
V 1.021	30/MAY/2021	[Bug fixed] 1. Fixed minor bugs
V 1.020	18/JAN/2021	[Bug fixed] 1. Add missed load parameters of ‘load default’ function [Function improved] 1. Stop all functions when switch to the SCRIPTER function
V 1.012	11/JAN/2021	[Bug fixed] [Function improved] 1. Display the waveform of the left and right channel of the audio analyzer. 2. Added the standalone function.
V 1.01	19/OCT/2020	[bug fixed] - Comma(,) and dot(.) problems in number expression
V 1.00	16/SEP/2020	Version 1.00 Release